ENVIRONMENTAL TESTING AND MEASUREMENT

Non-contact thermometers



C.A 871

- > Small and easy to handle
- > Simple to use
- > Ideal for all users

C.A 879

- > Specially designed for comfortable handling
- > Laser sight for precise targeting of the measurement area

| | | C.A 871 | C.A 879 |
|---------------------|------------------------|--|------------------------------|
| Specific | ations | | |
| D/S targeting ratio | | 8/1 | 12/1 |
| Emissivity | | Fixed: 0.95 | |
| Measurement range | | -40 °C to +538 °C | −50 °C to +550 °C |
| Resolution | | 0.1 °C to 100 °C 1 °C for other temperature | |
| Accuracy* | | ±2.5% ±2 °C | ±1.5% ±2 °C |
| Function | ns | | |
| | Laser sight | Ye | es |
| | Continuous measurement | Yes (continuous) | oress on trigger) |
| | Hold | Ye | es |
| | Measurement unit | °C / | ∕°F |
| Display | | LCD 2,000 counts with backlighting | |
| Dimensions / weight | | 160 x 82 x 41.5 mm / 180 g | 230 x 100 x 56 mm / 290 g |

^{*} Depending on measurement range. See operating manual for details.

State at delivery

- > C.A 871 delivered with carrying bag and 9 V battery
- > C.A 879 delivered with carrying bag and 9 V battery

References to order

> C.A 871

> P01651302Z

> C.A 879

> P01651805Z

Accessories/Replacement parts

9 V battery Carrying case

- > P01100620
- > P01298033




Non-contact thermometers

C.A 1864 & C.A 1866

- > Extensive temperature range: measure up to 1,000 °C
- > Variable emissivity ensuring inspections in line with reality
- > High distance/spot-size targeting ratio for greater accuracy
- > Set your alarm thresholds

| | C.A 1864 | C.A 1866 | |
|---------------------|---------------------------------------|--------------|--|
| Specifications | | | |
| D/S targeting ratio | 30/1 | 50/1 | |
| Emissivity | 0.1 to 1 | | |
| Measurement range | −50 °C to +1,000 °C | | |
| Resolution | 0.1 °C | | |
| Accuracy | -50 °C to −20 °C: ± 5 °C | | |
| | -20 °C to +200 °C: ±1.5 % R + 2 °C | | |
| | +200 °C to 538 °C: ±2.0 % R + 2 °C | | |
| | +538 °C to +1,000 °C: ±3.5 % R ± 5 °C | | |
| Functions | MAX, MIN, AVG, DIFF, HOLD | | |
| Alarms | High | High and low | |
| Measurement unit | °C, °F | | |
| Laser sight | Yes, class II laser | | |
| Display | 20,000 counts, backlighting | | |
| Dimensions / weight | 230 x 100 x 56 mm / 290 g | | |





Accessories/Replacement parts

9 V battery Carrying case > P01100620

> P01298033



State at delivery

- > C.A 1864 delivered in carrying case with operating manual and 9 V battery
- > C.A 1866 delivered in carrying case with operating manual and 9 V battery

References to order

> C.A 1864

> P01651813

> C.A 1866

> P01651814